



Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Re: TD10F Situation Report No. 14 as at 1200 Hours – Tuesday 14 February 2017

This situation report is to advise of the status of FRA's assets due to the effects of TD10F.

- Some roads still remain closed and impassable, especially in the Western and Northern Division. Please find alternative routes where possible and take extra caution.
- Members of the public travelling on the Bau Tikina Road are urged to exercise extreme caution. This follows the recent road slips that has necessitated additional barricades and one way restrictions on sections of this road.
- There are still a number of Irish crossings still flooded at the moment. FRA contractors will continue to carry out reinstatement work as the water level recedes.
- Higgins have commenced pothole repair works along Queens and Kings Road. Once this is under control they will move into the CBD areas and residential roads.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

WESTERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Rakiraki	Lau Road	Ford Crossing	Flooding	13/2/17-06.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nausori Road	Ford Crossing	Flooding	13/2/17-06.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nasau Road	Savusavu Crossing	Flooding	13/2/17-06.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nailuva Road	Burelevu Crossing	Flooding	13/2/17-06.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Nasomo	CH300	Culvert Washout	12/2/17-7am	Open to all traffic			13/02/17 5pm	Work in progress to reinstate culvert
Tavua	Qalela Rd	CH5500	Culvert Approach washout	12/2/17-7am	Open to all traffic			13/02/17 5pm	Work in progress to reinstate culvert
Tavua	Matacawa Rd	CH1500	Approach washout	12/2/17-7am	Closed to all traffic	Backfill Approach today	14/02/2017-5pm		
Ba	Navala Road	Navala Crossing	Crossing under water	12/2/17-7am	Open to all traffic			13/02/17 5pm	Water receded
Ba	Vutuni Road	3rd Crossing	Crossing under water	12/2/17-7am	Open to 4x4 and heavy vehicles only. Water level is high	Approach is being reinstated.	TBA		

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Ba	Yaloku Crossing	crossing	Crossing under water	12/2/17-7am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Cemetery road	crossing	Crossing under water	13.02.2017=7am	Open to 4x4 and heavy vehicles only. Water level is high	To be Advised When Water Recedes	TBA		
Ba	Koula Rd	Culvert	Road Drop out	12/2/17-7am	Closed to all traffic	Reinstate Culvert & Backfill when weather permits	TBA		
Lautoka	Navula Road		Road Drop out	12/02/17=7.15am	Closed to all traffic	Plant will be mobilised today 14/02/17 to reinstate	TBA		
Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Approach being reinstated today	TBA		
Nadi	Chunilal Rd	Chunilal Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Approach being reinstated today	TBA		
Nadi	Savalau Rd	Savalau Crossing No.2	Flooding	11/02/17 11am	Closed to all traffic	Approach being reinstated today	TBA		
Nadi	Togo Rd	Togo Cross Culvert	Washout/S cour	11/02/17 11.30am	Open to 4x4 vehicles only	To be reinstated	TBA		
Nadi	Navilawa Road	Crossing	Deck Damaged	13/02/2017 3pm	Open to 4x4 vehicles only. Deck is damaged	To be reinstated	TBA		
Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding, approach washout	7/2/17=7.30 am	Closed to all traffic	Approach was reinstated. Water level is high			
Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	12/02/17=7.30am	Closed to all traffic	Awaiting Water Level to Recede	14-Feb-17		
Sigatoka	Dreke Rd	Near the Village	Landslide	12/02/17=7.30am	Open to 4x4 vehicles only	Clear landslide	TBA		

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	12/02/17=7.30am	Closed to all traffic	Awaiting Water Level to Recede	14-Feb-17		
Sigatoka	Nasauco Rd	Nasauco	Very muddy	12/02/17=7.30am	Open to 4x4 vehicles only	Clear mud when rain stops	TBA		
Siagatoka	Balenabel Rd	Ford Crossing	High water level and strong current	12.02.2017 2.30pm	Closed to all traffic	Awaiting Water Level to Recede	14-Feb-17		

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

CENTRAL DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	14-Feb-17	Closed	Monitor water levels	Unknown		
Korovou	Navunisol Rd	Navunisol Crossing	Flooded	14-Feb-17	Closed	Monitor water levels	Unknown		
Korovou	UN1542R Nawiwaivusa Rd	Nawiwaivusa Crossing	Flooded	14-Feb-17	Closed	Monitor water levels	Unknown		
Korovou	Wairua Settlement Rd	Wairua Crossing	Flooded	14-Feb-17	Closed	Monitor water levels	Unknown		

EASTERN DIVISION

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Tavuki Road	Ch 9km Just before Baidamudamu Village	Culvert approach Washout	1200hrs 10/02/17	Road Only open to 4WD vehicles only	Attend and fix approach and washout	2/16/2017	0900hrs 16/02/17	
	Vunisea Jetty	Vunisea Jetty	Partial washout of causeway.	1200hrs 12/02/17	Jetty closed to vehicles	Attend and fix to partial washout on Jetty course way	2/14/2017	1700hrs 14/02/17	

NORTHERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
------------	-----------	----------------------	------------------	--------------------	---------------------	---	----------------------------	--------------------	--------------

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Labasa	Nakorotari Road	Navakuru Crossing	Approach Washout	3:00pm 07/02/17	Close d to all traffic	Reinstate Washout once water recedes. Water receded. Midday update 11/02/17 - approach washout again. Reinstate once water recedes	TBC		Pending
Natua	Drawa Road	Drawa Crossing	Approach Washout	8:00am 09/02/17	Close d to all traffic	Reinstate Washout once water recedes. Still closed as of 4:00pm 13/02/17	TBA		Pending
Natua	Zailav Road	Zailav Crossing	Underwater	8:00am 09/02/17	Open to all traffic	Still underwater at 4:00pm 10/02/17. Crossing still under water midday update 11/02/17. Still closed as of 4:00pm 13/02/17	TBA		Complete
Natua	Movo	50m	Collapse culvert	12:00pm 09/02/17	Close d to all traffic	Wait for flood waters to recede. Repair culvert. Still closed as of 4:00pm 13/02/17	TBA		Pending
Labasa	Vuniyalayala Road	Vuniyalayala Low Level Bridge Crossing	Concrete Bridge Deck has sustained significant damage.	4:00pm 09/02/17	Close d to all traffic	Inspection, design and repairs required to concrete bridge deck. Bridge closed indefinitely. NOTE: This is a loop road and the road is still open and accessible to all vehicles, but the bridge is closed to all traffic. Still closed as of 4:00pm 13/02/17	TBA		Pending
Natua	Nabouwalu Road	Nabouwalu - Daria Road	Saturated pavement causing boggy sections	4:00pm 11/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	TBA		Pending

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Natua	Korotari Road	Various locations	Boggy sections of road - difficult for buses and heavy vehicles. Bus service may not be running on Monday 13/02/17	4:00pm 12/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	TBA		Pending
Natua	Drawa Road	Drawa Crossing	Approach Washout	4:00pm 12/02/17	Closed to all traffic	Reinstate washout once water recedes	TBA		Pending
Natua	Naduri Road	Various locations	Saturated pavement causing boggy sections	4:00pm 12/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	TBA		Pending
Natua	Tabia Road	Various locations	Saturated pavement causing boggy sections	4:00pm 12/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	TBA		Pending
Natua	Dradramea Cir	Various locations	Saturated pavement causing boggy sections	6.00am 13/02/17	Drive with care	Pavement repairs once rain ceases	TBA		Pending
Natua	Lau rd	Various locations	Slippery areas. No bus service due to these conditions	9.00am 13/02/17	Open to 4x4 drive with caution	Metaling works once rain ceases	TBA		Pending
Natua	Dreketi Irrigation	Various locations	Boggy sections of road - difficult for buses and heavy vehicles. Complaint from DO's office. Itinerary for one of PM's visit(rice project)	9.00am 13/02/17	Open to 4WD. Drive with care	Metaling works once rain ceases	TBA		Pending

Situation Report TD10F- 14
12pm- Tuesday 14 February 2017

Natua	Nabouwalu Road	Sawani Crossing	Debris Pile Upstream	4:00pm 13/02/17	Open to all traffic	Remove debris	TBA		Pending
Natua	Nabouwalu Road	Nakorolevu Crossing	Debris Pile Upstream	4:00pm 13/02/17	Open to all traffic	Remove debris	TBA		Pending
Natua	Nabouwalu Road	Nakawakawa Crossing	Debris Pile Upstream	4:00pm 13/02/17	Open to all traffic	Remove debris	TBA		Pending
Natua	Koroinasolo	900m	Saturated pavement causing boggy sections		Open. Drive with care	Drainage & pavement repair			Pending
Natua	Korokadi Road	2km	Saturated pavement causing boggy sections		Open to 4x4 drive with caution	Drainage & pavement repair			Pending

-END-

For more information please contact the Communications Team at communications@fijiroads.org or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.