



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

Re: TD10F Situation Report No. 15 as at 1600 Hours – Tuesday 14 February 2017

This situation report is to advise of the status of FRA's assets due to the effects of TD10F.

- Some roads still remain closed and impassable, especially in the Western and Northern Division. Please find alternative routes where possible and take extra caution.
- Members of the public travelling on the Bau Tikina Road are urged to exercise extreme caution. This follows the recent road slips that has necessitated additional barricades and one way restrictions on sections of this road.
- There are still a number of Irish crossings still flooded at the moment. FRA contractors will continue to carry out reinstatement work as the water level recedes.
- Higgins have commenced pothole repair works along Queens and Kings Road. Once this is under control they will move into the CBD areas and residential roads.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

WESTERN DIVISION

| Depot | Road Name | Location Description | Status of Damage | Time/Date Reported | Advice to Motorists | FRA Contractors Action that Will be Taken | Expected Road Opening Date | Time/Date Resolved | How Resolved |
|----------|-----------------|----------------------|----------------------|--------------------|--|---|----------------------------|--------------------|--------------|
| Rakiraki | Lau Road | Fort Crossing | Flooding | 13/2/17-06.30am | Closed to all traffic | Awaiting Water Level to Recede | TBA | | |
| Rakiraki | Nausori Road | Fort Crossing | Flooding | 13/2/17-06.30am | Closed to all traffic | Awaiting Water Level to Recede | TBA | | |
| Rakiraki | Nasau Road | Savusavu Crossing | Flooding | 13/2/17-06.30am | Closed to all traffic | Awaiting Water Level to Recede | TBA | | |
| Rakiraki | Nailuva Road | Burelevu Crossing | Flooding | 13/2/17-06.30am | Closed to all traffic | Awaiting Water Level to Recede | TBA | | |
| Tavua | Matacawa Rd | CH1500 | Approach washout | 12/2/17-7am | Closed to all traffic | Backfill Approach today | 14/02/2017-5pm | | |
| Ba | Vutuni Road | 3rd Crossing | Crossing under water | 12/2/17-7am | Open to 4x4 and heavy vehicles only. Water level is high | Approach is being reinstated. | TBA | | |
| Ba | Yaloku Crossing | crossing | Crossing under water | 12/2/17-7am | Closed to all traffic | To be Advised When Water Recedes | TBA | | |
| Ba | Cemetery road | crossing | Crossing under water | 13.02.2017=7am | Open to 4x4 and heavy vehicles only. Water level is high | To be Advised When Water Recedes | TBA | | |
| Ba | Koula Rd | Culvert | Road Drop out | 12/2/17-7am | Closed to all traffic | Reinstate Culvert & Backfill when weather permits | TBA | | |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

| | | | | | | | | | |
|----------|---------------|-----------------------|----------------------------|------------------|--|--|--------------|--------------|--|
| Lautoka | Navula Road | | Road Drop out | 12/02/17=7.15 am | Closed to all traffic | Plant will be mobilised today 14/02/17 to reinstate | TBA | | |
| Nadi | Arolevu Rd | Arolevu Crossing | Flooding | 7/2/17=7.30am | Closed to all traffic | Awaiting Water Level to Recede. Debris to be cleared | TBA | | |
| Nadi | Chunilal Rd | Chunilal Crossing | Flooding | 7/2/17=7.30am | Closed to all traffic | Awaiting Water Level to Recede. Debris to be cleared | TBA | | |
| Nadi | Savalau Rd | Savalau Crossing No.2 | Flooding | 11/02/17 11am | Closed to all traffic | Awaiting Water Level to Recede. Debris to be cleared | TBA | | |
| Nadi | Togo Rd | Togo Cross Culvert | Washout/Scour | 11/02/17 11.30am | Open to all traffic | | 14/2/17 11am | 14/2/17 11am | Reinstated |
| Nadi | Wailoko Rd | Mud Pool Crossing | Flooding, pavement washout | 11/02/17 11.30am | Closed to all traffic | work in progress | 14/2/17 7pm | | |
| Nadi | Navilawa Road | Crossing | Deck Damaged | 13/02/2017 3pm | Open to 4x4 vehicles only. Deck is damaged | To be reinstated | TBA | | |
| Nadi | Namulomulo Rd | Namulomulo Crossing | Flooding, approach washout | 7/2/17=7.30am | Open to all traffic | | | 14/2/17 11am | Approach reinstated. Water level is normal |
| Sigatoka | Bukuya Rd | Nasivikoso crossing | Underwater by 1 M | 12/02/17=7.30 am | Closed to all traffic | Awaiting Water Level to Recede | 14-Feb-17 | | |
| Sigatoka | Dreke Rd | Near the Village | Landslide | 12/02/17=7.30 am | Open to 4x4 vehicles only | Clear landslide | TBA | | |
| Sigatoka | Wauosi rd | Wauosi crossing | Underwater by 0.5 M | 12/02/17=7.30 am | Closed to all traffic | Awaiting Water Level to Recede | 14-Feb-17 | | |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

| | | | | | | | | | |
|----------|---------------|---------------|------------------|-------------------|---------------------------|--------------------------------|-----------|--|--|
| Sigatoka | Nasauco Rd | Nasauco | Very muddy | 12/02/17=7.30 am | Open to 4x4 vehicles only | Clear mud when rain stops | TBA | | |
| Sigatoka | Balenabelo Rd | Ford Crossing | High water level | 12.02.2017 2.30pm | Closed to all traffic | Awaiting Water Level to Recede | 14-Feb-17 | | |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

CENTRAL DIVISION

| Depot | Road Name | Location Description | Status of Damage | Time/Date Reported | Advice to Motorists | FRA Contractors Action that Will be Taken | Expected Road Opening Date | Time/Date Resolved | How Resolved |
|---------|---------------------------|----------------------|------------------|--------------------|---------------------|---|----------------------------|--------------------|--------------|
| Korovou | Colata Cocoa Rd | Colata Crossing | Flooded | 14-Feb-17 | Closed | Monitor water levels | Unknown | | |
| Korovou | Navunisolé Rd | Navunisolé Crossing | Flooded | 14-Feb-17 | Closed | Monitor water levels | Unknown | | |
| Korovou | UN1542R Nawiwaivusa Rd | Nawiwaivusa Crossing | Flooded | 14-Feb-17 | Closed | Monitor water levels | Unknown | | |
| Korovou | Wairua Settlement Rd | Wairua Crossing | Flooded | 14-Feb-17 | Closed | Monitor water levels | Unknown | | |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

EASTERN DIVISION

| Depot Area | Road Name | Location Description | Status of Damage | Time/Date Reported | Advice to Motorists | FRA Contractors Action that Will be Taken | Expected Road Opening Date | Time/Date Resolved | How Resolved |
|------------|---------------|--|------------------------------|--------------------|--------------------------------|---|----------------------------|--------------------|--------------|
| Vunisea | Tavuki Road | Ch 9km Just before Baidamudamu Village | Culvert approach Washout | 1200hrs 10/02/17 | Road Only open to 4WD vehicles | Attend and fix approach and washout | 2/16/2017 | 0900hrs 16/02/17 | |
| | Vunisea Jetty | Vunisea Jetty | Partial washout of causeway. | 1200hrs 12/02/17 | Jetty closed to vehicles | Attend and fix to partial washout on Jetty course way | 2/14/2017 | 1700hrs 14/02/17 | |

NORTHERN DIVISION

| Depot Area | Road Name | Location Description | Status of Damage | Time/Date Reported | Advice to Motorists | FRA Contractors Action that Will be Taken | Expected Road Opening Date | Time/Date Resolved | How Resolved |
|------------|-----------------|----------------------|------------------|--------------------|-----------------------|--|----------------------------|--------------------|--------------|
| Labasa | Nakorotari Road | Navakuru Crossing | Approach Washout | 3:00pm 07/02/17 | Closed to all traffic | Reinstate Washout once water recedes. Water receded. Midday update 11/02/17 - approach washout again. Reinstate once water recedes | TBC | | Pending |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

| | | | | | | | | | |
|--------|-------------------|---|--|---------------------|------------------------------|---|-----|--------------------|----------|
| Natua | Drawa Road | Drawa Crossing | Approach Washout | 8:00am 09/02/17 | Closed to all traffic | Reinstate Washout once water recedes. Still closed as of 4:00pm 13/02/17 | TBA | | Pending |
| Natua | Movo | 50m | Collapse culvert | 12:00pm 09/02/17 | Open to all traffic | Wait for flood waters to recede. Repair culvert. Culvert installed. Road open as of 4:00pm 14/02/17 | TBA | 4:00pm 14/02/17 | Complete |
| Labasa | Vuniyalayala Road | Vuniyalayal a Low Level Bridge Crossing | Concrete Bridge Deck has sustained significant damage. | 4:00pm 09/02/17 | Closed to all traffic | Inspection, design and repairs required to concrete bridge deck. Bridge closed indefinitely. NOTE: This is a loop road and the road is still open and accessible to all vehicles, but the bridge is closed to all traffic. Still closed as of 4:00pm 13/02/17 | TBA | | Pending |
| Natua | Nabouwalu Road | Nabouwalu - Daria Road | Saturated pavement causing boggy sections | 4:00pm 11/02/17 | Open to 4WD. Drive with care | Pavement repairs once rain ceases | TBA | | Pending |
| Natua | Korokadi Road | Various locations | Boggy sections of road - difficult for buses and heavy vehicles. Bus service may not be running on Monday 13/02/17 | 4:00pm 12/02/17 | Open to 4WD. Drive with care | Pavement repairs once rain ceases | TBA | | Pending |
| Natua | Drawa Road | Drawa Crossing | Approach Washout | 4:00pm 12/02/17 | Closed to all traffic | Reinstate washout once water recedes | TBA | | Pending |
| Natua | Naduri Road | Various locations | Saturated pavement causing boggy sections | 4:00pm 12/02/17 | Open to 4WD. Drive with care | Pavement repairs once rain ceases | TBA | | Pending |



Situation Report TD10F- 15
4pm- Tuesday 14 February 2017

| | | | | | | | | | |
|-------|--------------------|----------------------|--|--------------------|--------------------------------|---|--------------------|--|---------|
| Natua | Tabia Road | Various locations | Saturated pavement causing boggy sections | 4:00pm 12/02/17 | Open to 4WD. Drive with care | Pavement repairs once rain ceases | TBA | | Pending |
| Natua | Dradramea Cir | Various locations | Saturated pavement causing boggy sections | 6.00am 13/02/17 | Drive with care | Pavement repairs once rain ceases | TBA | | Pending |
| Natua | Lau rd | Various locations | Slippery areas. No bus service due to these conditions. | 9.00am 13/02/17 | Open to 4x4 drive with caution | Metalling works once rain ceases | TBA | | Pending |
| Natua | Dreketi Irrigation | Various locations | Boggy sections of road - difficult for buses and heavy vehicles. | 9.00am 13/02/17 | Open to 4WD. Drive with care | Metalling works once rain ceases | TBA | | Pending |
| Natua | Nabouwalu Road | Sawani Crossing | Debris Pile Upstream | 4:00pm 13/02/17 | Open to all traffic | Remove debris | TBA | | Pending |
| Natua | Nabouwalu Road | Nakorolevu Crossing | Debris Pile Upstream | 4:00pm 13/02/17 | Open to all traffic | Remove debris | TBA | | Pending |
| Natua | Nabouwalu Road | Nakawaka wa Crossing | Debris Pile Upstream | 4:00pm 13/02/17 | Open to all traffic | Remove debris | TBA | | Pending |
| Natua | Koroinasolo | 900m | Saturated pavement causing boggy sections | | Open.drive with care | Drainage & pavement repair | TBA | | Pending |
| Natua | Korokadi Road | 2km | Saturated pavement causing boggy sections | | Open to 4x4 drive with caution | Drainage & pavement repair. Work estimated to be completed later tonight | 8:00pm 14/02/17 | | Pending |

-END-

For more information please contact the Communications Team at communications@fijiroads.org or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.