

Situation Report 11
9am – Saturday 20 October 2018

Re: Situation Report No. 11 as at 0800 Hours – Saturday 20th October 2018

This situation report is to advise of the status of FRA's assets after the heavy rain event:

Briefly on Central:

- Dawakoto Road – Open to all traffic – Flood water receded
- Buiduna Road – Open to all traffic – Flood water receded
- Muavesi Road – Open to all traffic – Flood water receded

Also note that Naboro Cocoa Road is now closed again due flood water rising. This is a result of continuous rain experienced in the Dawasamu area from last night.

- There is a slip before Nasavu Village Road on the right hand side on Sawani Serea Road. We have closed off one lane. Motorists are advised to proceed with caution.
- Motorists are advised not to drive into water of unknown depth and current, as this can be life threatening and avoid places of known historical flooding or low-lying areas
- The FRA is closely monitoring the situation of the roads in all divisions. For further queries please call our toll free number 5720 or send an email to info@fijiroads.org

Roads Closed in the Western Division:

- Burelevu Crossing on Nailuva Road
- Matewale Crossing in Nadroga/Navosa
- Savusavu Crossing Lawaki Rd (Dawa or Nasau)
- Nausori Crossing on Nausori Road
- Navuniyamunu Crossing on Ganilau Road- open to 4WD
- Burewai Crossing on Nakorotubu (Namarai Coastal Road) open to 4WD

Roads Closed in the Northern Division

- Matainadoi Crossing on Laekba Road in Labasa
- Ravuka Bridge on Lakeba Road in Labasa
- Sigawe Crossing on Namuavoivoi Road in Natua is open to 4WD only

***Refer to the table below for Central Division- changes highlighted in green**

Situation Report 11
9am – Saturday 20 October 2018

Central Division

Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date
Naboro Cocoa Road	Naboro Cocoa Crossing	Flooded Crossing	19/10/2018 16:19:00 a.m.	Closed to all Traffic	Monitor Flood Level	TBC
Unknown Nawiwaivusa Road	Waimalua Crossing	Flooded Crossing	10/17/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Vatulili Road	Waidradra Crossing	Flooded Crossing	10/15/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Colata Cocoa Rd	Colata Cocoa Crossing	Flooded Crossing	10/15/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Nasaibitu Road	Waisa Crossing	Flooded Crossing	16/10/2018 0830hrs	Closed to all Traffic	Monitor Flood Level	TBC
Navulokani Road	Waiwatu Crossing	Flooded Crossing	16/10/2018 0900hrs	Closed to all Traffic	Monitor Flood Level	TBC
Nairukuruku Road	Waima Crossing	Flooded Crossing	16/10/2018 1058hrs	Closed to all Traffic	Monitor Flood Level	TBC
Wailase Road	Nacokaika Crossing	Flooded Crossing	19/10/2018 10101hrs	Closed to all Traffic	Monitor Flood Level	TBC
Wailase Road	Nasi Crossing	Flooded Crossing	16/10/2018 1341hrs	Closed to all Traffic	Monitor Flood Level	TBC
Waidawara Road	Wainiuraura Crossing	Flooded Crossing	16/10/2018 1519hrs	Closed to all Traffic	Monitor Flood Level	TBC

Situation Report 11
9am – Saturday 20 October 2018

Navunisoile Road	Nakorovou Crossing	Flooded Crossing	10/17/2018 7:15	Closed to all Traffic	Monitor Flood Level	TBC
Wairua Settlement Road (Korovou)	Wairua Crossing	Flooded Crossing	10/17/2018 7:15	Closed to all Traffic	Monitor Flood Level	TBC
Navulokani Road	Waisa Crossings	Flooded Crossing	10/17/2018 8:53	Closed to all Traffic	Monitor Flood Level	TBC
Ovalau Circular Road	Namoli Flats	Flooded	10/18/2018 8:53	Closed to all Traffic	Monitor Flood Level	TBC
Wailoa Road	Matainasau Crossing	Flooded Crossing	10/17/2018 9:53	Closed to all Traffic	Monitor Flood Level. Reinstate washout crossing approaches	TBC
Sawanikula Bukunivatu Road	Wainiogai Crossing	Flooded Crossing	10/17/2018 10:06	Closed to all Traffic	Monitor Flood Level. Reinstate washout crossing approaches	TBC
Navutu Road	Waimale Crossing	Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Nabukaluka Delailasaku Road	Waisomo Crossing	Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Nataveya Road	Waila Crossing	Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Naidiridiri Road (Off Wainibuku Road)		Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC

Situation Report 11
9am – Saturday 20 October 2018

Muavesi Road	Sector 6 Crossing	Flooded Crossing	17/10/2018 13:33:00 p.m.	Open to all traffic	Monitor Flood Level	19/10/2018 17.57.00pm
Viria Road	Culvert Crossing	Flooded	17/10/2018 14:24:00 p.m.	Closed to all Traffic	Monitor Flood Level	TBC
Toga Road	Toga Crossing	Flooded Crossing	17/10/2018 19:39:00 p.m.	Closed to all Traffic	Monitor Flood Level	TBC
Buiduna Road	Buiduna Flats	Flooded	17/10/2018 20:59:00 p.m.	Open to all traffic	Monitor Flood Level	19/10/2018 17.57.00pm
Dawakoto Road	Dawakoto Flats	Flooded	10/18/2018 6:09	Open to all traffic	Monitor Flood Level	19/10/2018 17.57.00pm
Waila Feeder Road	Waila Feeder Road Flats	Flooded	10/18/2018 6:09	Closed to all Traffic	Monitor Flood Level	TBC
Lofua Farm Road	Saiyaro Crossing	Approach Washout	10/18/2018 6:59	Closed to all Traffic	Reinstate Crossing approaches	TBC
Sawani Sera Road	Waidracia Bridge	Flooded	10/18/2018 8:03	Closed to all Traffic	Reinstate Crossing approaches	TBC
Nataveya Road	Gusuitavaki Crossing	Flooded Crossing	10/18/2018 8:03	Closed to all Traffic	Monitor Flood Level	TBC
Lutu/Vuisiga Road	Wainivida Crossing	Flooded Crossing	10/18/2018 8:44	Closed to all Traffic	Monitor Flood Level	TBC
Nakadi Road	First Crossing	Flooding	10/18/2018 11:00	Closed to all Traffic	Monitor Flood Level	TBC
Nakini Road		Flooding	19/10/2018 15:35:00 p.m.	Closed to all Traffic	Monitor Flood Level	TBC
Wailoa Road	Naivucuni Crossing	Approach Washout	19/10/2018 07.32am	Closed to all Traffic	Reinstate washout crossing approaches	TBC
Namuamua Road	Wainiyavu Crossing	Approach Washout	19/10/2018 07.32am	Closed to all Traffic	Reinstate washout crossing approaches	TBC

Situation Report 11
9am – Saturday 20 October 2018