

Situation Report 13
9am – Sunday 21 October 2018

Re: Situation Report No. 13 as at 0900 Hours – Sunday 21st October 2018

This situation report is to advise of the status of FRA's assets after the heavy rain event:

- **Some roads have opened up in the Central Division as floodwaters have receded with associated restoration works completed.**
 - Wailoa Road at Naivucini Crossing – Open to all traffic – Flood water receded
 - Navutu Road – Open to all traffic – Flood water receded
 - Savu Road – Open to all traffic – Flood water receded
 - Naboro Cocoa Rd – Open to all traffic – Floodwaters receded
 - Navunisoale Road - Open to all traffic – Floodwaters receded
 - Nakini Road (near Naganivatu Village) – Open to all traffic – Floodwaters receded

- **Please be aware of the possibility of falling rocks on Kings Road at Naqia. We are urging the public to please be alert on the possibility of rock falls and landslides amidst heavy rain.**

- There is a slip before Nasavu Village Road on the right hand side on Sawani Serea Road. We have closed off one lane. Motorists are advised to proceed with caution.

- Motorists are advised not to drive into water of unknown depth and current, as this can be life threatening and avoid places of known historical flooding or low-lying areas

- The FRA is closely monitoring the situation of the roads in all divisions. For further queries please call our toll free number 5720 or send an email to info@fijiroads.org

Roads Closed in the Western Division:

- Burelevu Crossing on Nailuva Road
- Matewale Crossing in Nadroga/Navosa
- Savusavu Crossing Lawaki Rd (Dawa or Nasau)
- Nausori Crossing on Nausori Road
- Navuniyamunu Crossing on Ganilau Road- open to 4WD
- Burewai Crossing on Nakorotubu (Namarai Coastal Road) open to 4WD

***Refer to the table below for Central Division and Northern Division updates**

Situation Report 13
9am – Sunday 21 October 2018

Central Division

Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date
Naboro Cocoa Road	Naboro Cocoa Crossing	Flooded Crossing	19/10/2018 16:19:00 a.m.	Open to Traffic	Monitor Flood Level	21/10/2018 7.50am
Unknown Nawiwaivusa Road	Waimalua Crossing	Flooded Crossing	10/17/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Vatulili Road	Waidradra Crossing	Flooded Crossing	10/15/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Colata Cocoa Rd	Colata Cocoa Crossing	Flooded Crossing	10/15/2018 7:00	Closed to all Traffic	Monitor Flood Level	TBC
Nasaibitu Road	Waisa Crossing	Flooded Crossing	16/10/2018 0830hrs	Closed to all Traffic	Monitor Flood Level	TBC
Navulokani Road	Waiwatu Crossing	Flooded Crossing	16/10/2018 0900hrs	Closed to all Traffic	Monitor Flood Level	TBC
Nairukuruku Road	Waima Crossing	Flooded Crossing	16/10/2018 1058hrs	Closed to all Traffic	Monitor Flood Level	TBC
Wailase Road	Nacokaika Crossing	Flooded Crossing	19/10/2018 10101hrs	Closed to all Traffic	Monitor Flood Level	TBC
Wailase Road	Nasi Crossing	Flooded Crossing	16/10/2018 1341hrs	Closed to all Traffic	Monitor Flood Level	TBC
Waidawara Road	Wainiuraura Crossing	Flooded Crossing	16/10/2018 1519hrs	Closed to all Traffic	Monitor Flood Level	TBC

Situation Report 13
9am – Sunday 21 October 2018

Navunisoile Road	Nakorovou Crossing	Flooded Crossing	10/17/2018 7:15	Open to Traffic	Monitor Flood Level	21/10/2018 7.30am
Ovalau Circular Road	Namoli Flats	Flooded	10/18/2018 8:53	Closed to all Traffic	Monitor Flood Level	TBC
Wailoa Road	Matainasau Crossing	Flooded Crossing	10/17/2018 9:53	Closed to all Traffic	Monitor Flood Level. Reinstate washout crossing approaches	TBC
Sawanikula Bukunivatu Road	Wainiogai Crossing	Flooded Crossing	10/17/2018 10:06	Closed to all Traffic	Monitor Flood Level. Reinstate washout crossing approaches	TBC
Navutu Road	Waimale Crossing	Flooded Crossing	10/17/2018 10:54	Open to Traffic	Monitor Flood Level	21/10/2018 7.50am
Nabukaluka Delailasaku Road	Waisomo Crossing	Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Nataveya Road	Waila Crossing	Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Naidiridiri Road (Off Wainibuku Road)		Flooded Crossing	10/17/2018 10:54	Closed to all Traffic	Monitor Flood Level	TBC
Viria Road	Culvert Crossing	Flooded	17/10/2018 14:24:00 p.m.	Closed to all Traffic	Monitor Flood Level	TBC
Toga Road	Toga Crossing	Flooded Crossing	17/10/2018 19:39:00 p.m.	Closed to all Traffic	Monitor Flood Level	TBC
Waila Feeder Road	Waila Feeder Road Flats	Flooded	10/18/2018 6:09	Closed to all Traffic	Monitor Flood Level	TBC

Situation Report 13
9am – Sunday 21 October 2018

Lofua Farm Road	Saiyaro Crossing	Approach Washout	10/18/2018 6:59	Closed to all Traffic	Reinstate Crossing approaches	TBC
Sawani Sera Road	Waidracia Bridge	Flooded	10/18/2018 8:03	Closed to all Traffic	Reinstate Crossing approaches	TBC
Nataveya Road	Gusuitavaki Crossing	Flooded Crossing	10/18/2018 8:03	Closed to all Traffic	Monitor Flood Level	TBC
Lutu/Vuisiga Road	Wainivida Crossing	Flooded Crossing	10/18/2018 8:44	Closed to all Traffic	Monitor Flood Level	TBC
Nakadi Road	First Crossing	Flooding	10/18/2018 11:00	Closed to all Traffic	Monitor Flood Level	TBC
Nakini Road	Towards Naganivatu Village	Flooding	19/10/2018 15:35:00 p.m.	Open to Traffic	Monitor Flood Level	20/10/2018 4.15pm
Wailoa Road	Naivucuni Crossing	Approach Washout	19/10/2018 07.32am	Open to Traffic	Reinstate washout crossing approaches	21/10/2018 7.50am
Namuumua Road	Wainiyavu Crossing	Approach Washout	19/10/2018 07.32am	Closed to all Traffic	Reinstate washout crossing approaches	TBC
Savu Road	Savu Flats	Flooding	21/10/2018 07:30am	Closed to all Traffic	Monitor Flood Level	TBC
Nakini Road	Natoaika Bailey Bridge	Flooding	20/10/2018 05:25pm	Closed to all Traffic	Monitor Flood Level	TBC

Situation Report 13
9am – Sunday 21 October 2018

Northern Division

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved
Natua	Namuavoivoi	Sigawe Crossing	Flood water just above Bridge Deck		Open to 4WD only drive with care	Monitor Flood Water		
Taveuni	North Coastal Rd	Waibula Bridge	Flood water just above Bridge Deck		Open to traffic drive with care	Monitor Flood Water		
Taveuni	North Coastal Rd	Before Qeleni Village	Road Dropout	9.00am 20/10	Open to single lane only	Reinstate Road dropout - backfill with suitable material and armour rock coastal end	Restoration work in progress	6.00pm 21/10/18
Labasa	Urata Rd	Urata Crossing	Approach Washout	11.00am 20/10/18	Closed to traffic	Establish site this morning to commence repairs	2.00pm 21/10/18	
Labasa	Dreketilailai	Dreketilailai Crossing	Approach Washout	11.00am 20/10/18	Closed to traffic	Establish site this morning to commence repairs	2.00pm 21/10/18	

Situation Report 13
9am – Sunday 21 October 2018

Natua	Nabouwalu	Daria Crossing	Minor Approach Washout	3.00pm 20/10/18	Single lane open drive with care	Establish site this morning to commence repairs	2.00pm 21/10/18	
Labasa	Kelikoso	Kelikoso Bridge Near Village	Approach Washout	3.00pm 20/10/18	Closed to traffic	Establish site this morning to commence repairs	2.00pm 21/10/18	
Labasa	Qelemumu	Qelemumu Crossing	Underwater Alternative route open	6.00am 20/10/18	Closed to traffic	Monitor Flood Water		