

Situation Report 7
1pm – Thursday 18 October 2018

Re: Situation Report No. 7 as at 1300 Hours – Thursday 18th October 2018

This situation report is to advise of the status of FRA's assets after the heavy rain event:

- All roads in the Northern Division are now open except Sigawe Crossing on Namuavoivoi Road in Natua- this is CLOSED to all traffic.
- Road cavity near Nasau and Naqaidamu, with flooding on Sinuvaca culvert crossing in Koro Island. Please take extra.
- Motorists are advised not to drive into water of unknown depth and current, as this can be life threatening. Members of the public are advised to take extra caution, avoid places of known historical flooding or low-lying areas
- The FRA is closely monitoring the situation of the roads in all divisions. Shall you have any further queries please call our toll free number 5720 or send an email to info@fijiroads.org

New Road Closure Update for Central Division:

- Sawani Sera Road – Waidracia Crossing flooded – Closed to all traffic.
- Nataveya Road – Gusuitavaki Crossing Flooded – Closed to all traffic.
- Lutu/Vuisiga Road – Wainavida Crossing Flooded – Closed to all traffic.
- Sawani Serea Road – Before Nasavu Village Road – Half Road closed.
- Savu Road – Flooded - Is now Closed to all traffic.

Roads that are now open to traffic in Central Division:

- Beqa Road – Tubarua Crossing – Water has receded.
- Vunaniu Road – Vunaiu Crossing – Water has receded.
- Sote Road – Sote Bridge – Water has receded.
- Nukurua Road – Nabuni Culvert – Water has receded.
- Deepwater Road – Water has receded.

Roads Closed in the Western Division:

- Savusavu Crossing – Closed
- Burelevu Crossing – Closed
- Matewale Crossing on Valley Road Closed
- Katudrau – Closed to light vehicle
- Narara – 1st Crossing – closed to light vehicle
- Namunamu – 1st Crossing - Closed

Situation Report 7
1pm – Thursday 18 October 2018

Central Division

| Road Name | Location Description | Status of Damage | Time/Date Reported | Advice to Motorists | FRA Contractors Action that Will be Taken | Expected Road Opening Date |
|--------------------------|-----------------------|------------------|------------------------|------------------------------|---|----------------------------|
| Naboro Cocoa Road | Naboro Cocoa Crossing | Flooded Crossing | 10/15/2018 7:00 | Closed to all Traffic | Monitor Flood Level | TBC |
| Unknown Nawiwaivusa Road | Waimalua Crossing | Flooded Crossing | 10/17/2018 7:00 | Closed to all Traffic | Monitor Flood Level | TBC |
| Vatulili Road | Waidradra Crossing | Flooded Crossing | 10/15/2018 7:00 | Closed to all Traffic | Monitor Flood Level | TBC |
| Naivoco Road | Naivoco Crossing | Flooded Crossing | 10/17/2018 8:50 | Closed to all Traffic | Monitor Flood Level | TBC |
| Colata Cocoa Rd | Colata Cocoa Crossing | Flooded Crossing | 10/15/2018 7:00 | Closed to all Traffic | Monitor Flood Level | TBC |
| Nasaibitu Road | Waisa Crossing | Flooded Crossing | 16/10/2018 0830hrs | Closed to all Traffic | Monitor Flood Level | TBC |
| Navulokani Road | Waiwatu Crossing | Flooded Crossing | 16/10/2018 0900hrs | Closed to all Traffic | Monitor Flood Level | TBC |
| Nairukuruku Road | Waima Crossing | Flooded Crossing | 16/10/2018 1058hrs | Closed to all Traffic | Monitor Flood Level | TBC |
| Wailase Road | Nacokaika Crossing | Flooded Crossing | 19/10/2018 10101hrs | Closed to all Traffic | Monitor Flood Level | TBC |
| Wailase Road | Nasi Crossing | Flooded Crossing | 16/10/2018 1341hrs | Closed to all Traffic | Monitor Flood Level | TBC |
| Waidawara Road | Wainiuraura Crossing | Flooded Crossing | 16/10/2018 1519hrs | Closed to all Traffic | Monitor Flood Level | TBC |

Situation Report 7
1pm – Thursday 18 October 2018

| | | | | | | |
|---------------------------------------|---|------------------|-----------------------|--|---------------------|-----|
| Navunisole Road | Nakorovou Crossing | Flooded Crossing | 10/17/2018 7:15 | Closed to all Traffic | Monitor Flood Level | TBC |
| Wairua Settlement Road (Korovou) | Wairua Crossing | Flooded Crossing | 10/17/2018 7:15 | Closed to all Traffic | Monitor Flood Level | TBC |
| Savu Road | Culvert 5/2 | Flooded | 19/10/2018 11.01am | Closed to all Traffic | Monitor Flood Level | TBC |
| Savu Road | Near Junction Santani Ketan chool | Flooded | 19/10/2018 11.01am | Closed to all Traffic | Monitor Flood Level | TBC |
| Navulokani Road | Waisa Crossings | Flooded Crossing | 10/17/2018 8:53 | Closed to all Traffic | Monitor Flood Level | TBC |
| Ovalau Circular Road | Namoli Flats | Flooded | 10/18/2018 8:53 | Closed to all Traffic | Monitor Flood Level | TBC |
| Wailoa Road | Matainasau Crossing | Flooded Crossing | 10/17/2018 9:53 | Closed to all Traffic | Monitor Flood Level | TBC |
| Sawanikula Bukunivatu Road | Wainiogai Crossing | Flooded Crossing | 10/17/2018 10:06 | Closed to all Traffic | Monitor Flood Level | TBC |
| Ratu Kadavulevu Road | Ratu Kadavulevu Flats from RP 1.040 - 1.564 | Floodiing | 10/17/2018 10:22 | Open to 4 x 4 vehicles only. Proceed with Caution | Monitor Flood Level | TBC |
| Navutu Road | Waimale Crossing | Flooded Crossing | 10/17/2018 10:54 | Closed to all Traffic | Monitor Flood Level | TBC |
| Nabukaluka Delailasaku Road | Waisomo Crossing | Flooded Crossing | 10/17/2018 10:54 | Closed to all Traffic | Monitor Flood Level | TBC |
| Nataveya Road | Waila Crossing | Flooded Crossing | 10/17/2018 10:54 | Closed to all Traffic | Monitor Flood Level | TBC |
| Naidiridiri Road (Off Wainibuku Road) | | Flooded Crossing | 10/17/2018 10:54 | Closed to all Traffic | Monitor Flood Level | TBC |

Situation Report 7
1pm – Thursday 18 October 2018

| | | | | | | |
|--------------------------|-------------------|------------------|-----------------------------|---|---|------------|
| Visama Road | Visama Flats | Flooding | 10/17/2018 10:54 | Half Road Closed to Traffic. Proceed with caution. | Monitor Flood Level | TBC |
| Vuci South Road | Vuci South Flats | Flooding | 10/17/2018 10:54 | Half Road Closed to Traffic. Proceed with caution. | Monitor Flood Level | TBC |
| Waituri Road | Waituri Flats | Flooding | 10/17/2018 10:54 | Half Road Closed to Traffic. Proceed with caution. | Monitor Flood Level | TBC |
| Deepwater Road (Korovou) | | Flooding | 10/17/2018 10:54 | Open to all traffic | Monitor Flood Level | 10/18/2018 |
| Lomaivuna Loop Road | Toda Crossing | Flooded Crossing | 17/10/2018 13:24:00 p.m. | Closed to all Traffic | Monitor Flood Level | TBC |
| Muavesi Road | Sector 6 Crossing | Flooded Crossing | 17/10/2018 13:33:00 p.m. | Closed to all Traffic | Monitor Flood Level | TBC |
| Beqa Road | Tubarua Crossing | Flooded Crossing | 17/10/2018 14:24:00 p.m. | Open to all traffic | Monitor Flood Level | 10/18/2018 |
| Viria Road | Culvert Crossing | Flooded | 17/10/2018 14:24:00 p.m. | Closed to all Traffic | Monitor Flood Level | TBC |
| Vunaniu Road | Vunaniu Crossing | Flooded Crossing | 17/10/2018 14:51:00 p.m. | Open to all traffic | Monitor Flood Level and backfill scouring | 10/18/2018 |
| Sote Road | Sote Bridge | Flooded | 17/10/2018 16:09:00 p.m. | Open to all traffic | Monitor Flood Level | 10/18/2018 |
| Nukurua Road | Nabuni Culvert | Flooded | 17/10/2018 16:19:00 p.m. | Open to all traffic | Monitor Flood Level | 10/18/2018 |
| Toga Road | Toga Crossing | Flooded Crossing | 17/10/2018 19:39:00 p.m. | Closed to all Traffic | Monitor Flood Level | TBC |

Situation Report 7
1pm – Thursday 18 October 2018

| | | | | | | |
|-------------------|--------------------------------|--------------------------|-----------------------------|--|---|-----|
| Buiduna Road | Buiduna Flats | Flooded | 17/10/2018 20:59:00 p.m. | Closed to all Traffic | Monitor Flood Level | TBC |
| Sawani Serea Road | Naqali Flats | Flooded | 10/18/2018 6:09 | Closed to all Traffic | Monitor Flood Level | TBC |
| Dawakoto Road | Dawakoto Flats | Flooded | 10/18/2018 6:09 | Closed to all Traffic | Monitor Flood Level | TBC |
| Waila Feeder Road | Waila Feeder Road Flats | Flooded | 10/18/2018 6:09 | Closed to all Traffic | Monitor Flood Level | TBC |
| Delaikuku Road | Delaikuku Road Culvert | Approach Partial Washout | 10/18/2018 6:09 | Open to traffic proceed with caution | Monitor Flood Level | TBC |
| Lofua Farm Road | Saiyaro Crossing | Approach Washout | 10/18/2018 6:59 | Closed to all Traffic | Reinstate Crossing approaches | TBC |
| Sawani Sera Road | Waidracia Bridge | Flooded | 10/18/2018 8:03 | Closed to all Traffic | Reinstate Crossing approaches | TBC |
| Nataveya Road | Gusuitavaki Crossing | Flooded Crossing | 10/18/2018 8:03 | Closed to all Traffic | Monitor Flood Level | TBC |
| Lutu/Vuisiga Road | Wainivida Crossing | Flooded Crossing | 10/18/2018 8:44 | Closed to all Traffic | Monitor Flood Level | TBC |
| Sawani Serea Road | Before Nasavu Village Road RHS | Old Slip Site | 10/18/2018 8:44 | One Lane Closed. Open to traffic. Proceed with caution. | Erect Barrier Nettings and monitor slip | TBC |
| Nakadi Road | First Crossing | Flooding | 10/18/2018 11:00 | Closed to all Traffic | Monitor Flood Level | TBC |