

Situation Report 8
5pm – Monday 7 January 2019

Re: Situation Report No. 8 as at 1700 Hours – Monday 7 January 2019

This situation report is to advise of the status of FRA's assets due to the effect of TC Mona:

- 22 roads are closed in the Central, 8 roads closed in the North, 3 roads closed in the Eastern Division

- Kings Road is reduced to single lane at Naqia due to rock fall

- We are advising members of the public to exercise extreme caution and avoid crossing flooded areas.

- The FRA is closely monitoring the situation of the roads in all divisions. Shall you have any further queries please call our toll free number 5720 or send an email to info@fijiroads.org

NB: List of Roads Closed Due to Flooding

Situation Report 8
5pm – Monday 7 January 2019

Central Division

Province	Road Name	Location Description	Status of Damage	Date & Time Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date
Naitasiri	Vatulili Road	Waidradra Crossing	Flooded Crossing	1/4/2018 15:24	Closed	Monitor Flood Level	TBC
Tailevu	Colata Road	Colata Crossing	Flooded Crossing	1/5/2019 7:55	Closed	Monitor Flood Level	TBC
Tailevu	Nawiwaivusa Road	Waimalua Crossing	Flooded Crossing	1/5/2019 7:56	Closed	Monitor Flood Level	TBC
Tailevu	Off Navunisole Road	Nakorovou Crossing	Flooded Crossing	1/5/2019 7:57	Closed	Monitor Flood Level	TBC
Serua	Vunaniu Road	Vunaniu Crossing	Flooded Crossing	1/5/2019 8:58	Restricted to Light Vehicles	Monitor Flood Level	TBC
Naitasiri	Wailase Road	Nasi Crossing	Flooded Crossing	1/5/2019 11:07	Closed	Monitor Flood Level	TBC
Naitasiri	Rewasau Rd	towards Rewasau Village	Road Slip	1/5/2019 11:33	Closed	Site Assessment	TBC
Naitasiri	Wailoa Road	Matainasau Crossing	Flooded Crossing	1/5/2019 15:20	Closed	Monitor Flood Level	TBC
Naitasiri	Sawanikula Bukunivatu Road	Sawanikula Crossing	Flooded Crossing	1/5/2019 15:27	Closed	Monitor Flood Level	TBC
Tailevu	Naboro Cocoa Road	Naboro Crossing	Flooded Crossing	1/5/2019 14:05	Closed	Monitor Flood Level	TBC
Naitasiri	Nakorosule - Nawaisomo Road	Waibalavu Lailai Crossing	Flooded Crossing	1/6/2019 10:07	Closed	Monitor Flood Level	TBC

Situation Report 8
5pm – Monday 7 January 2019

Tailevu	Nasaibitu Road	Waisa Crossing	Flooded Crossing	1/6/2019 9:27	Closed	Monitor Flood Level	TBC
Naitasiri	Navulokani Road	Waiwatu Crossing	Flooded Crossing	1/6/2019 11:37	Closed	Monitor Flood Level	TBC
Naitasiri	Nabukaluka Delailasakau Road	Nasele Crossing	Flooded Crossing	1/6/2019 14:50	Closed	Monitor Flood Level	TBC
Tailevu	Vugalei Cocoa Road	Veisa Crossing	Flooded Crossing	1/6/2019 17:55	Closed	Monitor Flood Level	TBC
Tailevu	Kings Road	Naqia Village	Fallen boulders blocking road way	1/7/2019 7:20	Restricted to Single Lane	TM P setup and crew mobilised to push boulders off road	1/7/2019 12:00
Naitasiri	Wailase Road	Nacokaika Crossing	Flooded Crossing	1/7/2019 9:45	Closed	Monitor Flood Level	TBC
Naitasiri	Viria Village Road	Nakuta Crossing	Flooded Crossing	1/7/2019 9:14	Closed	Monitor Flood Level	TBC
Naitasiri	Nauluvatu Road	Nauluvatu Flats	Flooded Road	1/7/2019 9:19	Closed	Monitor Flood Level	TBC
Namosi	Namuamua Road	Wainiyavu Crossing	Scoured Approaches	1/7/2019 11:44	Closed	Setup TMP and Reinstate Approach	TBC
Namosi	Nabukaluka Delailasakau Road	near Delailasaku Village	Overslip	1/7/2019 15:10	Restricted to Single Lane	Setup TMP and Clear Slip Debris	TBC
Namosi	Nabukaluka Delailasakau Road	near Naseuvou Village	Overslip	1/7/2019 15:10	Restricted to Single Lane	Setup TMP and Clear Slip Debris	TBC
Naitasiri	Nukuloa Road	near Naseuvou Village	Flooded Crossing	1/7/2019 15:10	Closed	Monitor Flood Level	TBC

Situation Report 8
5pm – Monday 7 January 2019

Eastern Division

Province	Road Name	Location Description	Status of Damage	Date & Time Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date
Lomaiviti	Koro Circular Road	Nasau Crossing	Crossing Washout	1/4/2019 10:30	Closed to all Traffic	Monitor Flood Level	
Lomaiviti	Koro Circular Road	Nasoni Crossing	Flooded Crossing	1/4/2019 10:30	Closed to all Traffic	Monitor Flood Level	TBC
Lomaiviti	Koro Circular Road	Waitabu Crossing	Flooded Crossing	1/4/2019 10:30	Closed to all Traffic	Monitor Flood Level	TBC
Lomaiviti	Koro Circular Road	Jetty to Kade Nairukuruku Hill	Slipover and falling bolders	1/6/2019 10:30	Single Lane	Remove Slipover	

Situation Report 8
5pm – Monday 7 January 2019

Northern Division

Province	Road Name	Location Description	Status of Damage	Date & Time Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date
Macuata	Branch off Nakelikoso Road	Nubu Crossing	Flooded Crossing	1/4/2019 10:45	Closed to all Traffic. Alternative Route Available	Await flood waters to recede and assess approaches. FHH to monitor flood water levels and organise repairs	TBC
Cakaudrove	Bucalevu Rd	Bucalevu Crossing	Underwater	1/5/2019 10:00	Closed to traffic	Await Flood water to recede, backfill bridge approach	TBC
Cakaudrove	North Coastal Rd	Waibula Bridge	Underwater	5/01/2019 12.00pm	Closed to traffic	Await Flood water to recede	TBC
Cakaudrove	Nabouwalu	Daria Crossing	Approach Washout	5/01/2019 6;15pm	Open to 4WD. Drive with care	Approach reinstatement once flood waters recede.	
Cakaudrove	Nabouwalu	Sawani Crossing	Approach Washout and debris removal	5/01/2019 6;15pm	Open to 4WD. Drive with care	Approach reinstatement once flood waters recede and debris removal	
Cakaudrove	Qaranivai		Saturated pavements and slippery road conditions on various sections.	4/01/2019 8;15pm	Open to 4WD. Drive with care	Pavement repairs and spot metalling. Work in progress	

Situation Report 8
5pm – Monday 7 January 2019

Macuata	Coqeloa Road	Qeileimumu Crossing	Underwater	6/01/2019 10;47am	Open to traffic. Drive with care	Await water to recede.	TBC
Macuata	Nakelikoso Road	Nakelikoso Crossing	Underwater	6/01/2019 10;47am	Open to traffic. Drive with care	Await water to recede.	TBC
Macuata	Nakorotari	Navakuru Crossing	Underwater	6/01/2019 10;47am	Close to Traffic	Await water to recede.	TBC
Cakaudrove	Bagata	Bagata Crossing	Underwater	1/6/2019 13:51	Close to Traffic	Await water to recede.	TBC
Bua	Nabouwalu	Nabouwalu Bridge Approach	Hole on Bridge approach	1/6/2019 14:30	Open to traffic. Drive with care	Backfill reinstatement	TBC
Macuata	Zailav	Zailav Crossing	Crossing underwater	1/6/2019 15:17	Close to Traffic	Await water to recede.	TBC
Cakaudrove	Nakobo	Bagasau Crossing	Approach Washout	1/7/2019 7:51	Close to traffic	Await water to recede and start approach reinstatement.	TBC
Macuata	Naduna Road	Nakama Crossing	Debris on bridge deck	1/7/2019 7:51	Open to traffic	Await water to recede and start removal of debris	TBC
Macuata	Satulaki Road	Satulaki splash crossing	Flooded	1/7/2019 7:51	Closed to traffic	Await water to recede and start removal of debris	TBC